National Transportation Safety Board	NTSB	ID· /	ATL89FA071	1	Aircraft Registration Number: N9330B							
National Transportation Safety Board FACTUAL REPORT			rrence Date: 01/11/1989			Most Critical Injury: Serious						
34. 101 11 101 10												
ÄYIATION		Occurr	ence	Type: Accid	ent	Investigated By: NTSB						
Location/Time												
Nearest City/Place	State	Zip Code Local Time Time Zone										
MADISON	NC	27025 0728 EST										
Airport Proximity: Off Airport/Airstrip	Distar	nce From	n Lar	nding Facility:	0	Direction Fron	n Airpor	t: 0				
Aircraft Information Summary												
Aircraft Manufacturer				Model/Series	3			Type of Aircraft				
CESSNA				208B				Airplane				
Sightseeing Flight: No			Air	Medical Tr	ansport Flight: No	1						
Narrative												
Brief narrative statement of facts, conditions and circumstand	ces perti	nent to the	accid	lent/incident:								
	I	FACTU	AL I	REPORT - A	VIATION				Page 1			

Page 1

National Transportation Safety Board
FACTUAL REPORT

NTSB ID: ATL89FA071

Occurrence Date: 01/11/1989

AVIATION	AVIATION Occurrence					ce Type: Accident						
Landing Facility/Approach In	formation	•				'						
Airport Name		P	Airport ID:	Airport Eleva	tion	Run	way Used	Runwa	y Lengt	h	Runway Width	
ROCKINGHAM COUNTY/SHIL	_OH		NC14	676 Ft.	MSL	31		5200			100	
Runway Surface Type: Asphalt												
Runway Surface Condition: Dry												
Type Instrument Approach: SDF												
VFR Approach/Landing: None												
Aircraft Information												
Aircraft Manufacturer CESSNA			Model 208B	/Series					Serial 208B	Number 30053		
Airworthiness Certificate(s): Norm	nal		•									
Landing Gear Type: Tricycle												
Homebuilt Aircraft? No	ircraft? No Number of Seats: 2				Certified Max Gross Wt.					er of En	gines:	1
				Engine Manufacturer: Model/Series: P&W PT6A-114							Rated 600	l Power: HP
- Aircraft Inspection Information												
Type of Last Inspection			Date of Last Inspection Time Sin			nce Last Inspection			Airfram	ne Tota	al Time	
AAIP			11/23/198	11/23/1988 101				101 Ho	Hours 896 Hours			96 Hours
- Emergency Locator Transmitter (	ELT) Information											
ELT Installed? Yes	ELT Operat	ed? Yes	i		ELT	Aided i	n Locating Ad	cident S	ite? Ye	s		
Owner/Operator Information												
Registered Aircraft Owner  Street Address P.O. BOX 35408												
ATLANTIC AERO, INC			City  GREENSBORO							State		Zip Code
	GREENSBORO NC 27425 Street Address											
Operator of Aircraft P.O. BOX 25408												
ATLANTIC AERO, INC				City GREENSBORO							- 1	Zip Code 27425
Operator Does Business As:  Operator Does Business As:  Operator Designator Code:												
- Type of U.S. Certificate(s) Held:						-						
Air Carrier Operating Certificate(s)	: On-demand Air	Гахі										
Operating Certificate:				Operator C	Certific	ate:						
Regulation Flight Conducted Unde	r: Part 135: Air Ta	axi & Co	mmuter	•								
Type of Flight Operation Conducted	d: Unknown											
		FACTU	AL REPO	RT - AVIATI	ON							Page 2

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: ATL89FA071

Occurrence Date: 01/11/1989

AVIATI	Occurrence Type: Accident											
First Pilot Information												
Name					City				State	Dat	e of Birth	Age
On File					On File	e			On File	Or	n File	22
Sex: M Seat Occupied	: Left	Prir	ncipal Profes	sion: Civiliar	n Pilot			Certi	ficate Nu	ımber:	On File	
Certificate(s): Flight Instructor; Commercial												
Airplane Rating(s): Multi	i-engine Lar	nd; Single-e	ngine Land									
Rotorcraft/Glider/LTA: None	9											
Instrument Rating(s): Airpl	ane											
Instructor Rating(s): Airpl	ane Single-	engine										
Type Rating/Endorsement for Accident/Incident Aircraft? No  Current Biennial Flight Review?												
Medical Cert.: Class 1	Medica	l Cert. Status	S: Valid Med	dicalw/ wa	ivers/lim.		Dat	e of Las	st Medica	ıl Exan	n: 06/18/19	88
	•						•					
- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night	Instrument Ight Actual Simulated			Rotorci	otorcraft Glider		Lighter Than Air
Total Time	2100	360	1900	300	50	500						
Pilot In Command(PIC)	1800	350										
Instructor												
Last 90 Days												
Last 30 Days  Last 24 Hours												
Seatbelt Used? Yes	Shou	Ider Harness	Head? Vac		Tox	ricology F	Performed	No.		Seco	nd Pilot? <b>N</b> o	\
Gearbeit Osed: 163	31100	idei Hairiess	Oseu: 165		1102	acology i	CHOIIICG	INO		00001	na i not: MC	,
Flight Plan/Itinerary												
Type of Flight Plan Filed: IF	R											
Departure Point					Sta	ate	Airport Id	Airport Identifier		Departure Time		Time Zone
ROANOKE							ROA			0620		EST
Destination State Airport Identifier												
GREENSBORO NC GSO												
Type of Clearance: IFR												
Type of Airspace: Class	G											
Weather Information												
Source of Briefing: Flight	Service Stat	tion										
Method of Briefing:												
			FACTUAL	REPORT -	- AVIATI	ON						Page 3

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: ATL89FA071

Occurrence Date: 01/11/1989

Occurrence Type: Accident

Weather	Information												
WOF ID	Observation Time	Time Zone	WOF	Elevation	on	WOF D	WOF Distance From Accident Site						Э
GSO	0650	EST		926 Ft.	MSL				20 NM			206 Deg.	Mag.
Sky/Lowes	Sky/Lowest Cloud Condition: Unknown 0 Ft. AGL Condition of Light: Dawn												
Lowest Ce	eiling: Obscured	g: Obscured 100 Ft. AGL Visibility: 0 SM Altimeter: 30.00							30.00	"Hg			
Temperatu	ure: 2 °C	Dew Point:		2 °C	Wind	Direction:	: 20			Dei	nsity Altitude:	950	Ft.
Wind Spee	ed: 4	Gusts:			Weath	ner Condt	ions at Ac	cident S	ite: Instrum	ent C	Conditions		
Visibility (R	RVR): 0 Ft.	. Visibility	(RVV)	0	SM	Intensit	y of Precip	oitation:	Unknown				
Restriction	ns to Visibility: Fog												
Type of Pre	ecipitation: None												
Accident	Information												
Aircraft Dar	mage:		Air	craft Fire	ə:				Aircraft Exp	losio	n		
Classificati	ion:												
- Injury Sur	mmary Matrix	Fatal	Serious	Mino	r	None	TOTAL						
First Pi	lot		1					1					
Second	d Pilot			<u> </u>									
Studen	nt Pilot			T									
Flight In	nstructor												
Check	Pilot												
Flight E	Engineer												
Cabin /	Attendants												
Other C	Crew												
Passen	ngers	† †		<del>                                     </del>	$\neg$								
- TOTAL /	ABOARD -		1					1					
Other C		0	C	,	0			0					
- GRANE	D TOTAL -	0	1		0			1					
		<u>'</u>					•	•					

National Transportation Safety Board

FACTUAL REPORT AVIATION NTSB ID: ATL89FA071

Occurrence Date: 01/11/1989

Occurrence Type: Accident

A 1						
Adm	ทา	ictrai	ב אול	Into	\rma	ıtınn
Aun	III I	เงแฉ	แงษ	HILL	лпо	ılıvı

Investigator-In-Charge (IIC)

WALTER G. STINER

Additional Persons Participating in This Accident/Incident Investigation:

REYNOLD BISHOP FAA NORTH CAROLINA WINSTON-SALEM, NC